

ENGINEERING CHANGE NOTICE

Date: 03.02.27		ECN #: 514			
Project No.: D350-591		Created By: #	Checked By: 4P		
Project Name: 350 STEPS.		Approved By: # (proj. manager)	Approved By: N/A (management if req'd)		
Description of Change: RELEASE DEO 9248 REV. B DSI 9249 REV. B D3065 REV. A2 D3077 REV. A2					
} ECF MADE AN ERROR ON SLOT SIZE. NEEDS TO BE 14 mm INSTEAD OF 10.4 mm					
Notification/Acceptance	Affected	Authorization			
QA	✓	P301-457			
Production	✓				
Planning	✓				
Marketing	✓				
Engineering Actions	Yes	No	Responsible	To happen by:	Complete
Update Blue File		✓			
Update Pink File		✓			
Update D-Part Master Binder	✓		DS	03.02.27	03.02.27 #
Update Grey Project Binder	✓		DS	03.02.27	03.02.27 #
Update DEO Binder	✓		DS	03.02.27	03.02.27 #
Update Master Document List		✓			03.02.27 #
Update Drawing Approval Record	✓		DS	03.03.27	04.04.23 #
Update Change Record Form	✓		DS	03.02.27	03.02.27 #
Move Electronic File	✓		DS	03.02.27	03.02.27 #
Notify TCA of Change	✓		DS	03.03.27	04.04.23 #
Notify FAA of Change		✓			
Update QSI 021		✓			
Update QSI 036		✓			
Scan Documents		✓			
Update MIS Database		✓			
Update Access Database		✓			
Verification ARC		✓			
Notes:					
- SEE ECN # 510 - UPDATE PROGRAMS FOR D3077-1 + D3065-5 AGAIN - COPY OF DSI 9249 REV. B HAS BEEN SENT TO ECF TO FIX STEPS @ ECF. - MAKE NEW TOOL WITH INCREASED SLOT SIZE (14mm LONG) SIMILAR TO EXISTING TOOL - RE-MODIFY ALL D350-591-211/-212/-213/-214/-215/-216 + 704A 41 640 007 / 008 IN PROGRESS + IN STOCK PER DEO 9248 REV. B WITH NEW TOOL - ALL STEPS AFFECTED REMAIN AT CAG 001 BECAUSE ALL STEPS ARE BEING MODIFIED.					